

Risk Management Department 201 West Burleigh Boulevard - Tavares, FL 32778-2496 (352) 253-6600 - Fax: (352) 253-6674 - www.lake.k12.fl.us

Occupant Name: Address: City:	Mascotte Charter 460 Midway Aver Mascotte	nue l	nspection Date: nspectionType: nspected By:	10/6/2020 ACFI Inspection Joey Graham
Insp. Result	Location	Code Set	Code	July Granan
Deficiency	01-115 Custodial Laundry	FL NFPA 01 2015 Chapter 11 Building Services	11.5.4 - Maintenance - Repair exhaust for kiln.	
Inspector Comments: Repair dryer exhaust vent line behind dryer.				
Deficiency	01-126B Restroom	FL NFPA 101 2015 Chapter 7 Means of Egress	7.2.1.5.1 - Maintenance - Door drags on frame - must be adjusted to open freely.	
	Inspector Comments: Door drags on frame.			
Deficiency	01-133 Custodial Storage	FL NFPA 101 2015 Chapter 7 Means of Egress	7.9.2.1.1 - Maintenance - Repair emergency light - path of egress at floor level.	
	Inspector Comments: The wall pack emergency light does not work.			
Deficiency	01-146 Mechanical Room	FL NFPA 101 2015 Chapter 7 Means of Egress	7.9.2.1.1 - Maintenance - Repair emergency light - path of egress at floor level.	
	Inspector Comments: The wall pack emergency light does not work.			
Deficiency	01-158A Kiln Room	FL NFPA 01 2015 Chapter 13 Fire Protection Systems	13.6.4.1.1 - Maintenance - Fire extinguisher date is expired.	
	Inspector Comments:	Fire extinguisher is out of dat	e	
Deficiency	01-212 Electrical Room	FL NFPA 101 2015 Chapter 7 Means of Egress	7.9.2.1.1 - Maintenance - Repath of egress at floor level.	epair emergency light -
	Inspector Comments: The wall pack emergency light does not work.			
Deficiency	02-104 PE Storage	FL NFPA 101 2015 Chapter 7 Means of Egress	7.9.2.1.1 - Maintenance - Repath of egress at floor level.	epair emergency light -
	Inspector Comments: The wall pack emergency light does not work.			

Inspector Comments: I found a plug in type air freshener in building 01-103A Extended Day Care room. Please remind staff that theses type devices are not allowed.

Inspector will return on or after 11/9/2020

Thank you for your cooperation in keeping our facility safe.

Principal Mayhugh OR Company Principal Mayhugh - Rego Representative:

10/6/2020

Inspector:



Ref: 188